

Douglas County Solid Waste Transfer Station Locations

Camas Valley TS #314 350 Camas Valley Transfer Road Permit # 249
Located off State Highway 42 near MP 56.5 approximately 1 mile east of Camas Valley. Turn South on Camas Valley Transfer Road (Co. rd. 214). *23 miles from landfill*

Canyonville TS #305 600 Jordan Creek Road Permit # 284
Take I-5 exit 98 and go west on Canyonville-Riddle Road (Co. rd. 21) approximately 1.5 miles. Turn left on Jordan Creek Road (Co. rd. 205) and go 0.5 mile. *27 miles from landfill*

Elkton TS #320 250 Elkton Transfer Road Permit # 314
Located off State Highway 38 near MP 33 approximately 3 miles west of Elkton. Turn north on Elkton Transfer Road (Co. rd. 320). *43.5 miles from landfill*

Glendale TS #344 240 Glendale Transfer Road Permit # 280
From the North take I-5 exit 86, turn left and go over freeway overpass and turn right on Rancho Road (Co. rd. 303) for 2.5 miles. Take a right on Barton Road (Co. rd. 97) and go back over freeway. Take a left on Glendale Transfer Road (Co. rd. 344). *39 miles from landfill*
From the South take exit 83, turn left on Barton Road (Co. rd. 97) and go over freeway overpass and turn left on Glendale Transfer Road (Co. rd. 344).

Glide TS #318 13921 Glide Transfer Road Permit # 258
Located off State Highway 138 near MP 12 approximately 6 miles west of Glide. Turn south on Glide Transfer Road (Co. rd. 318). *16.5 miles from landfill*

Myrtle Creek TS #345 300 Myrtle Creek Transfer Road Permit # 262
Take I-5 exit 108 to Myrtle Creek, take first left after crossing river on Dole Road (Co. rd. 14) and go approximately 0.5 mile. Turn right on Myrtle Creek Transfer Road (Co. rd. 345). *14 miles from landfill*

Oakland TS #346 220 Oakland Transfer Road Permit # 268
Go north on Old Highway 99N out of Oakland for approximately 0.5 mile to Green Valley Road (Co. rd. 23), turn left and go 0.5 mile to Manning Road (Co. rd. 168). Turn right on Manning Road and go about 0.5 mile to end of road. *21 miles from landfill*

Reedsport TS #329 300 Reedsport Landfill Road Permit # 464
East of Reedsport approximately 1 mile on State Highway 38 to Scholfield Road (Co. rd. 55) 0.25 mile to Reedsport Landfill Road (Co. rd. 329). *74.5 miles from landfill*

Roseburg TS #300 165 McLain West Ave Permit # 477

South of Roseburg at I-5 Exit 121 (McLain Avenue) and follow Roseburg Transfer Station signs.

Roseburg Landfill #342 384 McLain West Ave Permit # 265

South of Roseburg at I-5 Exit 121 (McLain Avenue), go uphill to the west after exiting and follow Roseburg Landfill signs.

Tiller TS #343 150 Tiller Transfer Road Permit # 251

East on Tiller Trail Hwy (Co. rd. 1) for 26.5 miles. Turn left on South Umpqua Road (Co. rd. 46) go approximately 4 miles to Tiller Transfer Road (Co. rd. 343). *52 miles from landfill*

Yoncalla TS #396 555 Yoncalla Transfer Road Permit # 281

Take I-5 Exit 150 then go north on Eagle Valley Road (Co. rd. 389) for approximately 3 miles to Yoncalla Transfer Road (Co. rd. 296). *33.5 miles from landfill*

Solid Waste O&M office at 433 Rifle Range Road is 2 miles east of I-5 exit 124 and 4.5 miles from Landfill